

Re-engineered Components Increase Slurry Pump Repair Interval

Rapid Prototyping and Materials Upgrades Save US\$240 000 Every Two Years

- **The Challenge:** A U.S. chemical plant was experiencing severe erosion on its butanol catalyst recycle slurry pump. The erosion resulted in poor pump performance and reduced unit throughput. Hydraulic degradation was so extreme the pump was pulled from service and refurbished every four to five months. Despite the use of super hard overlays and high velocity oxygen fuel (HVOF) spray coatings, the plant was unable to increase the mean time between repairs (MTBR).
- **The Solution:** At the request of plant operators, Flowserve engineers developed a solution that dramatically improved the MTBR from 4.5 months to 24 months while keeping the repair cost approximately the same. Incorporating rapid prototyping techniques from the Flowserve Component Technology Group (CTG), the solution included significant improvements to the pump's hydraulic components as well as a boron diffusion surface treatment for improved erosion resistance.

With the MTBR of its butanol catalyst recycle slurry pump averaging 4.5 months, one U.S. Gulf Coast chemical plant needed a longer-term solution to its persistent erosion problem. In addition to inflating maintenance costs, the erosion problem was negatively impacting unit throughput as a result of the slurry pump's rapid performance degradation. Manufactured by a large competitor of Flowserve, the 12% chrome pump was costing the plant approximately US\$40 000 at each overhaul. Refurbishment typically involved overlaying the wetted components with Stellite[®] 6 or applying HVOF spray coatings to enhance hardness and erosion resistance, but these measures provided only temporary relief.

Desperate for a more sustainable and less costly alternative, plant operators approached Flowserve to repair the damage and develop a solution.

® Stellite is a registered trademark of Deloro Stellite.

A Re-engineered Solution

To start, Flowserve acquired and examined one of the chemical plant's severely eroded pumps. Using three-dimensional mapping technology, Flowserve engineers created highly accurate models of the casing, cover and impeller. These models were used to produce 12% chrome castings with hydraulics comparable, if not superior, to the competitor's original product.

As an added benefit to the client, the Flowserve team redesigned the new pump components to accept a power end upgrade that would enable the pump to use the same mechanical seal and power end as a Flowserve-manufactured slurry pump already installed at the plant. This change enabled the plant to reduce its spare parts inventory, including a mechanical seal valued at US\$15 000.



Experience In Motion





With the new castings in hand, Flowserve technicians applied a boron diffusion treatment to all wetted surfaces. Not a coating but a through hardening technique wherein the microstructure of the base metal is metallurgically altered, the boron diffusion process significantly increases the surface hardness, and, therefore, the erosion resistance of treated components.

To prevent internal eddy currents from creating erosion points between mating pieces, a phenomenon identified during examination of pump remains, Flowserve engineers added integral wear rings on the pump casing, cover and impeller. All wear rings were hardened via direct laser deposition (DLP) to help maintain the proper running clearances for optimum hydraulic performance.

Casings Before and After





Impellers Before and After





Bulletin FSG-SS-019 (E/A4) Printed in USA. March 2011. © Flowserve Corporation

To find your local Flowserve representative:

For more information about Flowserve Corporation, visit www.flowserve.com or call +1 937 890 5839.

The Results

The solution developed by Flowserve dramatically increased the MTBR from 4.5 months to 24 months, while keeping the cost of repair approximately the same.

FINANCIAL BENEFITS	
Before Upgrade	
MTBR	4.5 months
Cost/Repair	US\$40 000
Biannual Repair Cost	US\$213 333
After Upgrade	
MTBR	24 months
Cost/Repair	US\$45 000
Biannual Repair Cost	US\$45 000
Annual Inventory Savings	US\$36 000
Total Biannual Savings	US\$240 333
Pump Upgrade Cost (one-time)	US\$60 000
Payback Period	0.49 years

USA and Canada Flowserve Corporation

5215 North O'Connor Blvd. Suite 2300 Irving, Texas 75039-5421 USA Telephone: +1 937 890 5839

Europe, Middle East, Africa Flowserve Corporation Parallelweg 13 4878 AH Etten-Leur The Netherlands Telephone: +31 76 502 8100

Latin America

Flowserve Corporation Martín Rodriguez 4460 B1644CGN-Victoria-San Fernando Buenos Aires, Argentina Telephone: +54 11 4006 8700 Telefax: +54 11 4714 1610

Asia Pacific

Flowserve Pte. Ltd. 10 Tuas Loop Singapore 637345 Telephone: +65 6771 0600 Telefax: +65 6862 2329

flowserve.com